Drain: OVERMAN - HARVEY Drain #: 37


Improvement/Arm: ARM | RELOCATION

Operator: J. LIVING STON Date: 15-18-2004

Drain Classification: Urban/Rural Year Installed: 1976

GIS Drain Input Checklist

- Pull Source Documents for Scanning
- Digitize & Attribute Tile Drains
- Digitize & Attribute Storm Drains
- Digitize & Attribute SSD
- Digitize & Attribute Open Ditch
- Stamp Plans
- Sum drain lengths & Validate
- Enter Improvements into Posse
- Enter Drain Age into Posse
- Sum drain length for Watershed in Posse
- Check Database entries for errors




Gasb 34 Footages for Historical Cost Drain Length Log

Drain-Improvement: Overman - HARVEY - ARM | RELOCATION

		Length			the like of the big se	
Orain Type:	Size:	Longin	Length (DB Query)	Length Reconcile	i	
			, , , , , , , , , , , , , , , , , , , ,	TACCOTICITE	Price:	Cost:
ncp	12"	744'	744'		725/sf	F3C./\
	15"	305'	305		9.50/1	5394°
	21"	410'	410'		14.25/1	5842:
	364	160'	160'		32·25/1f	5160
					00 //3	3160
OPEN DITCH		1095:36	1025.36	-70'	19.55/If	21,414.8
					7.7	4, 417
						

	Sum:	2714.36	2444.56	-70'	\$ 46, 708.29
Final Report: 2	714.86				·
Comments:					 .



Kenton C. Ward, Surveyor

773-6110 Ext. 19

Noblesville, Ind. 46060 September 28, 19881

To: Hamilton County Drainage Board

Re: Overman Harvey Drain

In 1976 Village Farms Section 2 was constructed in Section 14, T 18 N, R 3 E. The area in which this subdivision was platted was the same location in which Arm 1 of the Frank Overman Drain was located. At this time the said Arm was destroyed without Drainage Board approval.

Attached is a plan showing the storm sewer located in this subdivision.

I have marked in red the portion of this storm sewer which is close to the location of what was the Arm of the Overman Ditch.

I believe that the storm sewer which is described below should be considered as the relocated Arm 1 of the Overman Drain. This Arm begins in a catch basin approximately 80 feet west of the northeast corner of lot 153 of Village Farms Section 2, thence run east 444 feet in a 12" RCP to a catch basin in the north east corner of lot 146 of said subdivision, thence S 00° 44' E in a 12" RCP 300 feet to a catch basin, thence S 18° 23' W in a 15" RCP 165 feet to a catch basin, thence 140 feet S 32° 15' E in a 15" RCP to a catch basin. The storm sewer then turns N 71° 02' E and runs 185 feet in a 21" RCP to a curb inlet then 25' in a 21" RCP to another curb inlet, thence 200' in a 21" RCP to a outlet empting into a surface mater swale/retention area.

The swale runs S 00° 44' E 105 feet, S 13° 45' E 175.6', S 02° 26' W 166.76', S 25° 00' W 448 feet to a inlet. Thus in a 36" RCP S 20° 00' E 65' to a man hole thence S 22° 00' E 95' in a 36" RCP to an outlet in an open drain. Then running approximately 200' in the open ditch to the lake.

This system for the most part is in good working order. However there does exist two problems which need to be taken care of. One of these occurs at the outlet of the 36" RCP. At this point a load of riprap should be placed below the outlet in the channel to prevent erosin.

The other is more serious. There are several areas along the swale at which standing water occurs. To try to solve this problem the developer put in a 6" SSD along the swale which empties into the 36" RCP. This did not solve the problem. In my opinion, because of what I've seen, the tile was improperly installed. I believe this tile should be investigated and if necessary either relaid or replaced with another. Doing this along with putting in french drains should relieve this problem.

The original Arm 1 consisted of 24+67 feet of tile. The proposed subsitute consists of 2714.36 feet of ditch.

Kenton C. Ward, Surveyor

KCW/jg

