
GIS Drain Input Checklist

- Pull Source Documents for Scanning
- Digitize & Attribute Tile Drains
- Digitize & Attribute Storm Drains
- Digitize & Attribute SSD
- Digitize & Attribute Open Ditch
- Stamp Plans
- Sum drain lengths & Validate
- Enter Improvements into Posse
- Enter Drain Age into Posse
- Sum drain length for Watershed in Posse
- Check Database entries for errors





Gasb 34 Footages for Historical Cost Drain Length Log

Drain-Improvement: John OSBORN - BRIDLEBOURNE AKM

Drain Type:	Size:	Length	Length (DB Query)	Length Reconcile	Price:	Cost:
						OUSI.
RCP	12"	22'	22'		7.25/f	159.50
	15"	332	332'		9.50/1	3154
	18"	428'	428'		10.50/1f	4494.
· · · · · · · · · · · · · · · · · · ·	21"	32'	32		14.55/IF	456:=
	244	320'	320'		18:=/f	5760=
A Dr. L			_		•	
OPEN DITCH		11/11	uu'		19.55/1	21720 =
						" - "" - "
		·				

	Sum:	2245'	2245		\$ 35,743.55
Final Report:	2245'	_	·		
Comments:				•	
			·		

FINAL INSPECTION OF JOHN OSBORN REGULATED DRAIN

Bridlebourne Subdivision Project No. 575

10/31/89 3:30 p.m.

Sunny - 70 degrees Last precipitation - 7" snow on 10/17/89

Inspector: Designer:

Bruce A. Nicholson Bruce A. Nicholson

Structure No. 109:

End section installed, rip-rap installed, rip-rap consists of rocks up to about 3' square. A trash rack made of #3 rebar sits over the end of the pipe; debris caught on the rack is backing up water 3"-4". Pipe is clean with a small amount of flow.

Structure No. 108A:

Structure added in the field, rip-rap installed around beehive casting, pipe entering from south (Walnut Creek Woods), all pipes clean, small amount of flow.

Structure No. 108:

Straw bales installed around beehive casting. Pipes are clean with small amount of flow.

Structure No. 107:

Straw bales installed around beehive casting. Pipes are clean with small amount of flow. Several holes above pipe (trench collapse?) between structures 107 and 106.

Structure No. 106:

Straw bales installed around beehive casting. Pipes are clean with small amount of flow.



Structure No. 105:

Straw bales installed around beehive casting. Pipes are clean with small amount of flow. Water can be heard running into pipe (from field tile?). Area between structures 105 and 104 has been seeded and straw-mulched.

Structure No. 104:

Straw bales installed around beehive casting. Pipes are clean with small amount of flow. Water can be heard running into pipe (from field tile?). Area between structures 104 and 103 has been seeded and straw-mulched.

Structure No. 103:

Straw mulch installed around beehive casting. Pipes are clean with small amount of flow. Water smells slightly septic. Area between structures 103 and 102 has been seeded and straw-mulched.

Structure No. 102:

Straw mulch installed around beehive casting. Pipes are clean with small amount of flow. A 10" (+/-) plastic pipe enters the north side of the manhole, apparently from a new lake to the north. Area between structures 102 and 101 has been seeded and straw-mulched.

Structure No. 101:

End section installed, rip-rap installed. Some erosion rills are present around end section, no trash has collected. Water depth in pipe is approx. 6" apparently due to conditions downstream of Towne Road. Effluent from pipe is milky-gray, small amount of flow. Some trash has collected in the twin metal culverts under Towne Road. The twin culverts have been extended to the west. The extensions are of questionable stability in high flow situations.

MOVI.

returned in the second

CERTIFICATE OF COMPLETION AND COMPLIANCE

TO: HAMILTON COUNTY SURVEYOR

RE: John Osborn Drain, Bridlebourne Sections 2 & 3 Arm

I hereby certify that:

- 1.) I am a Registered Land Surveyor in the State of Indiana,
- 2.) I am familiar with the plans and specifications for the above referenced subdivision,
- 3.) I have personally observed a/h/1/s/p/e/t/1/s/fi the completion of the Drainage Facilities for the above referenced subdivision, and
- 4.) To the best of my knowledge, information and belief, the Drainage Facilities within the subdivision has been installed and completed in conformity with all plans and specifications except as noted on the attached final inspection report.

Signature:	Date: 11/7/89
Type or Printed Name: John V. Schneider	
Business Address: 3020 North Post Road	
Indianapolis, IN 4622	6
Telephone: 898-8282	
S C HAMMAN	INDIANA REGISTRATION NUMBER S0115
SEAL SO115	

WILLIAM SURVEYOR





Kenton C. Ward, Surveyor

Phone (317) 776-8495

Fax (317) 776=9628

Suite 146 One Hamilton County Square Noblesville, Indiana 46060=2230 May 10, 1996

To: Hamilton County Drainage Board

Re: John Osborn Drain Bridlebourne Arm

Attached are plans, asbuilts, certificate of completion & compliance, and other information for Bridlebourne sections 2-6. An inspection of the drainage facilities for these sections has been made and the facilities were found to be complete and acceptable. Asbuilts were completed for sections 5,6, and the offsite for Larkspur section 1 located in Bridlebourne sections 5 & 6. Asbuilts could not be obtained for sections 2,3 & 4, however, these sections were inspected and built according to plan.

The portion of drain to be regulated were those outlined in my original reports dated January 7, 1988 and December 22, 1994. However, these portions within Bridlebourne Sections 5 and 6 that were constructed as offsite for Larkspur Section 1 are included in my final report to the Board for the section dated NAY 2,1996. The totals listed below are those in sections 2,3, and 4. They are as follows:

Open Ditch-1111 feet 12" RCP-22 feet 15" RCP-332 feet

18" RCP-428 feet 21" RCP-32 feet 24" RCP-320 feet

The length of drain described above is 2245 feet.

The non-enforcement for sections 2,3,4,5 and 6 were approved by the Board at its meetings on July 24, 1989; November 11, 1991; and March 27, 1995.

The bonds or letters of credit for these sections have expired.

I recommend the Board approve the drains construction as complete and acceptable.

Sincerely,

This copy printed from the Digital Archive of the Hamilton County Surveyor's Office; One Hamilton County Surveyor's One Hamilton County Sur

Kenton C. Ward

Hamilton County Surveyor

