

Source Document Log
Source Document Discrepancy Log

Drain: CENTENNIAL DRAIN

Main/Arm Name	Document Name	Document ID	Info From Document	If Applicable	
				Document w/ Discrepancy	Description of Discrepancy
CENTENNIAL TOWNHOMES - SECTION 1	SURVEYOR'S REPORT	12/19/01			
	SURVEYOR'S REPORT	9/25/02			
	AS BUILTS	753.008			
	BOND	8355955			
	CERT. OF COMPLIANCE	2/23/01			
SECTION 1	SURVEYOR'S REPORT	10-16-98		SURVEYOR'S REPORT 7-11-01	LENGTHS OF 24" PIPE FROM STR 202 TO 200 WERE PLACED IN CENTENNIAL TOWNHOMES SECTION 1
	SURVEYOR'S REPORT	7-11-01		AS BUILTS	
	AS BUILTS	753.001			
	BOND	1264104 + 126411			
	CERT. OF COMPLIANCE	6-26-01			
SECTION 2	SURVEYOR'S REPORT	6-20-00			
	SURVEYOR'S REPORT	10-22-02			
	AS BUILTS				
	BOND	152887 152888 + 152889			
	CERT. OF COMPLIANCE	3/31/01			

Source Document Log
Source Document Discrepancy Log

Drain: CENTENNIAL DRAIN

Main/Arm Name	Document Name	Document ID	Info From Document	If Applicable	
				Document w/ Discrepancy	Description of Discrepancy
SECTION 3	SURVEYOR'S REPORT	8-14-00		SURVEYOR'S REPORT 6-5-03	SURVEYOR'S REPORT SHOWS LENGTH OF 2,136.2' FOR
	SURVEYOR'S REPORT	6-5-03		AS BUILTS	24" PIPE.
	AS BUILTS	753.003			AS BUILTS SHOW LENGTH OF 2,136.8 WHICH IS CORRECT.
	BOND	885956S			
	CERT. OF COMPLIANCE	3-31-01			
SECTION 4	SURVEYOR'S REPORT	11-14-00			
	SURVEYOR'S REPORT	6-5-03			
	AS BUILTS	753.004			
	BOND	885934S			
	BOND	885956S			
	CERT. OF COMPLIANCE	7/9/01			
CENTENNIAL TOWNHOMES-SECTION 2	SURVEYOR'S REPORT	7-21-02		SUR REPORT	S/R - INCORRECT 12" PIPE LENGTH
	SURVEYOR'S REPORT	10-30-03		AS BUILTS	
	AS BUILTS	753.010			
	BOND	887161S			
	CERT. OF COMPLIANCE	8-17-02			

