Drain:	Woodhaven Drain			
Improvement-Arm:	U S 421 Road Improvements			
Date Approved:	April 14, 2008			
Dr	ain Input Checklist			
Create Regulated Drain Record in	Posse			
Drain Type Outlet (Tab) Outlet Attached Location Twp Certification Drain Number • Enter Improvement Arm in Posse (Construction Amount = Storm Drain • Scan Documents Surveyor's Report Engineer's Estimate Notices Findings and Order Petition	April 15, 2008 April 15, 2008 April 25, 2008 Earthwork)			
Create Posse Inspection Job				
Enter into Watershed Summary Sp.	readsheet			
Check for Vacation of Drain & Ma	p Changes			
Check Drainage Easement Classific	cation			
Sum drain length & Validate in GIS	S			
• Enter New Watershed Length into	Posse			
Create Boundary of Improvement i	n GIS			

Gasb 34 Footages for Historical Cost Drain Length Log

Drain-Improvement:	US 47	21 Road	1 Juprou	eneuts	LWOOD	Thaven)
			V			
Drain Type:	Size:	Length	Length (DB Query)	Length Reconcile	Prices	Cost:
RLP	15"	58'	58'	B	950 A	#551 ==
RLP RLP RLP	27"	1601	160	φ	#2150 H	* 3408°°
PLP	30'	129'	129'	ø	*2460 If	#551 == #3408 == #3173 45
	Sum:	312				*7132 45
Final Report: 312						
Comments:						



Kenton C. Ward, CFM Surveyor of Hamilton County Phone (317) 776-8495 Fax (317) 776-9628

Suite 188
One Hamilton County Square
Noblesville, Indiana 46060-2230

To: Hamilton County Drainage Board

November 14, 2007

Re: US 421 Road Improvements

Attached are plans, and other information for the US 421 Road Improvement project. An inspection of the drainage facilities for this project has been made and the facilities were found to be complete and acceptable.

This report will serve as an initial and final report for this construction. This road project began just north of 121st St. and continued South to five hundred feet south of 106th St. During this construction two regulated drains were affected. Those drains are as follows:

Park Northwestern Drain

Hamilton Business Park Arm: The project removed 130ft of open ditch, 75ft of 42"x 30" RCP, 80' of 42" X 27" RCP, 42' of 26" x 45" RCP and structure 100.

West Carmel Center Block C: The project removed 27' of open ditch.

The road improvements added the following drain: 142' open ditch on the West side of US 421, 35' of 36" RCP on the existing pipe coming from structure 43, and 144ft of 5' x 3' Box culvert under US 421. Overall, the road improvement project installed 321 feet of drain.

The road improvement project removed 354 feet of existing drain and installed 321 feet of new drain. Therefore the Park Northwestern drain had a loss of 33 feet of drain.

Woodhaven Drain

The project removed 35' of 15" CMP between existing structure 119 and existing structure 1. The drain was then extended from existing structure 1 to new structure 269 with 58 feet of 15" RCP. The drain is then outleted from structure 269 to 274A. This added 160' of 27" RCP and 129' of 30" RCP. Therefore, the project added 312 feet to the drain's overall length.

I recommend the Board approve the drain's construction as complete and acceptable.

This project was performed by INDOT. Therefore, performance bonds were not required. Also, since the work was performed within the INDOT right of way and was paid for by INDOT, this meets the terms as set out in IC 36-9-27-52.5 for a non-noticed hearing before the Drainage Board

I recommend the Board approve the drain's reconstruction and accept the work as complete and acceptable.

Sincerely

Kenton C. Ward, CFM Hamilton County Surveyor

KCW/slm