

Source Document Log
Source Document Discrepancy Log (Over)

Drain: OF HENLEY

#	Main/Arm Name	Document Name	Document ID	Info From Document
1	OF HENLEY	COMMISSIONER'S REPORT	5-29-1908	
2		SURVEYOR'S REPORT	9-25-1981	
3	EXTENSION	SURVEYOR'S REPORT	9-25-1981	
4		SURVEYOR'S REPORT	10-7-1982	
5		PROFILE OF OF HENLEY	6-1981	
6		LOCATION PLAN	6-1981	
7		SCS LETTER TO DRAIN. BD	7-10-1981	
8		SURVEYOR'S REPORT	11-14-2000	VACATION STA 8+60 - 11+50
9		SURVEYOR'S REPORT	6-1-2000	VACATION OF TILE THRU SADDLE CREEK SEC 1 & 3
10		SURVEYOR'S REPORT	8-12-02	VACATION OF TILE THRU SADDLE CREEK SEC 10
11	AUTUMN WOOD FARMS	SURVEYOR'S REPORT	4-6-1987	
12		SURVEYOR'S REPORT	7-6-1988	
13		CERT. OF COMPLETION & COMPLIANCE	9-10-1987	
14		ASBUILTS	597	
15		SURVEYOR'S REPORT	7-14-2000	VACATION OF TILE THROUGH SADDLE CREEK SEC 7, 8 & 9
16		ASBUILTS	960324-20500	" " " " " " " " " "
17		SURVEYOR'S REPORT	6-1-2000	VACATION OF TILE THROUGH SADDLE CREEK SEC 1 & 3
18	SADDLE CREEK SEC 3	SURVEYOR'S REPORT	3-22-1999	

Source Document Log
Source Document Discrepancy Log (Over)

Drain: OF HULLY

#	Main/Arm Name	Document Name	Document ID	Info From Document
19	SADDLE CREEK SEC3	SURVEYOR'S REPORT	6-1-2000	
20		BOND	127486	
21		CERT. OF COMPLETION & COMPL.	8-20-1999	
22		AS BUILTS	960324-2000	
23		SURVEYOR'S REPORT	6-2-2000	LENGTH OF SEC 4 - TO CALCULATE % OF BOND AMOUNT
24	SADDLE CREEK SEC1	SURVEYOR'S REPORT	8-22-1996	
25		SURVEYOR'S REPORT	2-1-1999	
26		BOND	54-081815	
27		CERT. OF COMPLETION & COMPLIANCE	7-23-1998	
28		AS BUILTS	960324-2000	
29	CARMEL W. ELEMENTARY	SURVEYOR'S REPORT	7-8-1992	
30		SURVEYOR'S REPORT	10-6-1997	
31		ASBUILT STRUCTURES	N/A	
32		ASBUILTS	1184	
33	DEBBIE KITCHENS	SURVEYOR'S REPORT	12-14-1998	
		SURVEYOR'S REPORT	11-14-2000	
		CERT. OF COMPLETION & COMPLIANCE	16-23-2000	
		ASBUILTS	97.0906	