

Drain: Saddle Creek Drain

Improvement-Arm: Ditch Road Improvements (141st St. to 146th St.)

Date Approved: June 9, 2008


Drain Input Checklist

- Create Regulated Drain Record in Posse _____
 - Drain Type
 - Outlet (Tab)
 - Outlet Attached
 - Location
 - Twp
 - Certification
 - Drain Number

- Enter Improvement Arm in Posse _____
 (Construction Amount = Storm Drains, Erosion Control, Sub-surface drain & Earthwork)

- Scan Documents _____
 - Surveyor's Report
 - Engineer's Estimate
 - Notices
 - Findings and Order
 - Petition

- Create Posse Inspection Job _____
- Enter into Watershed Summary Spreadsheet _____
- Check for Vacation of Drain & Map Changes _____
- Check Drainage Easement Classification _____
- Sum drain length & Validate in GIS _____
- Enter New Watershed Length into Posse _____
- Create Boundary of Improvement in GIS _____



Kenton C. Ward, CFM
Surveyor of Hamilton County
Phone (317) 776-8495
Fax (317) 776-9628

Suite 188
One Hamilton County Square
Noblesville, Indiana 46060-2230

June 5, 2008

TO: Hamilton County Drainage Board

RE: Saddle Creek Drain, Ditch Road Improvements from 141st St. to 146th St.

Attached are petition, plans, and other information for the Ditch Road Improvement from 141st St. to 146th St. The reconstruction was petitioned by the City of Carmel. An inspection of the drainage facilities for this project has been made and the facilities were found to be complete and acceptable.

This report will serve as an initial and final report for this reconstruction. This road project began just north of 141st St. north to 146th St. During this construction the Saddle Creek Drain was affected. Those changes are as follows:

Saddle Creek Drain

Saddle Creek Section 5 Arm: The project removed drain between Structures 717-717A. as shown on Sheet C201 of the plans prepared by Paul I. Cripe, Inc., Job No. 960324-20000, dated asbuilt August 20, 1999. As a result, 14' of 12" RCP was removed from this drain. A new inlet was set where Structure 717 was. Also removed was the 463 feet of 6" SSD that outleted into Structure 717. Therefore, the road improvement project removed a total of 477 feet from the Saddle Creek Drain. This is shown on Sheets 6 & 7 of the plans prepared by RW Armstrong project No. 04-06 file stamped April 11, 2005.

Upon approval of the reconstruction I recommend the Board approve the drain's construction as complete and acceptable.

The work was completed within the right of way owned by the City of Carmel and paid for by the City. Therefore, the project falls under the requirements as set out in IC 36-9-27-52.5. I recommend the Board approve the project at this time.

Sincerely,

A handwritten signature in black ink, appearing to read 'Kenon C. Ward', written over the word 'Sincerely,'.

Kenon C. Ward, CFM
Hamilton County Surveyor

KCW/pll