
Drain: OUVER SHEEMALER	Drain #: 12
Improvement/Arm: dettal Sarray	
Operator: J. Livi-16 Steel	Deter 6 11
Drain Classification: Urban/Rural Y	ear Installed:

## **GIS Drain Input Checklist**

- Pull Source Documents for Scanning
- Digitize & Attribute Tile Drains
- Digitize & Attribute Storm Drains
- Digitize & Attribute SSD
- Digitize & Attribute Open Ditch
- Stamp Plans
- Sum drain lengths & Validate
- Enter Improvements into Posse
- Enter Drain Age into Posse
- Sum drain length for Watershed in Posse
- Check Database entries for errors




ł

## <u>Gasb 34 Footages for Historical Cost</u> <u>Drain Length Log</u>

Drain-Improvement: OLIVER SHOEMAKER - John Sultran

<u>.</u>		Length	Length	Longth	Bally and a start of the	
Drain Type:	Size:		(DB Query)	Length Reconcile		
					Price:	Cost:
RCP	30"	85'	85'			r
					24.00/4	2091-
STEEL	24"	67'	67'		Fin 11	
					50-5/4	3358=
						·
						<u> </u>
						- <u></u>
· .						
· · · · · · · · · · · · · · · · · · ·						
	Sum:	152'	1521			5441.
al Report:		<b>-</b> .			·/	<u>- (                               </u>
nments:	· <u>·······························</u> ·					
Enno do R.	Euns of n	tomeral ex	E CILA A			
	STICK	-136 - 00	STEEL PIDE	1 Ref	HULL EL	TRADE
SIF CONST	WCTED PRI	OR TO 1980	2		The ext	



To: Hamilton County Drainage Board

Re: Oliver Shoemaker Drain

Recently while preparing the new Delaware Township Drainage map I research a long standing problem in regard to the Oliver Shoemaker Drain. The problem is that there exists no description for this drain. The only description which exists is for the 1916 repair of the drain also known as the John Sutton Arm. This Arm was to begin West of Sta 58 of the Shoemaker. It also was to run North of the existing Shoemaker and enter the Shoemaker at Sta 94+50. In 1931 the Shoemaker was extended to Sta 131+26 where it intersects Briton Brankh. The existence of two drains have been verified by locating both at the Rail Road and the catch basin at Sta 0 of the Sutton Arm only has one tile which runs to the South West, no other tile enters this structure. The 1931 map by Horney also shows two tiles and the approximate location of the Shoemaker North of 141st Street.

I have shown what I believe to be the location of the Shoemaker on the attached mylar. By measuring from Sta 58 on the South side of 141st Street, along where the tile has been location Sta 0 of the Shoemaker would be approximately 1850 feet East of the North West corner of 20-19-5. The tile has been located at this point and a breather has been installed. (See W.O. #81-003) Arm #2 is shown as

indicated on the 1931 map and the 1932 County Drain map. No work order can be found on this part of the drain. Arm #1 is shown as a private drain on the 1932 drain map. However, a breather has been installed at the Mayhew/Stewart fence line. Also it is shown as part of the legal drain on the 1971 drain map. I believe that this should be a part of the legal drain from a point 800' West of the North East corner NW4 NE4 20-19-5 to the point of intersection with the main ditch. Arm #3 is in a fashion shown on the 1971 map and has had work done on it. (See W.O. #75-33) Also, in the 1916 description of the Sutton Arm a 10 inch tile from the North intersects this Arm at Sta 62+67. (See Ditch Repair Book 4, Page 83.) Although the 1971 map shows the tile running North to 146th Street. No record of repair exists beyond about 600 feet North of 141st Street on this Section. Therefore, I recommend that the description of the Arm be as follows: Begin at a point 450 feet North and 650 feet East of the center of 19-19-5 and run South to the intersection of the Suttong Arm at Sta 62+67. The approximate lengths of the main Arms and total would be as follows:

Shoemaker	13126 feet
Sutton Arm	3650 feet
Arm 1	1800 feet
Arm 2	2800 feet
Arm 3	<u>1000 feet</u>
Total	22376 feet

Kenton C. Ward,

County Surveyor

KCW/jg

24204 Aur \$2:30 FILED MAR 6 - 1931 CUR Human nd discharge the same of مى ئەلىپ ئەتلەر يېتىنى ئۇسىرىتارىخى ئار 36115 **APCHEN** RECORD The 23 day of lips 4. D. 1931, all 34 clock 17 M., and M. C. Maria St page 75-70 recorded in grouts Requester dismilton County 2 0 This copy printed from the Digital Archive of the Hamilton County Surveyor's Office; One Hamilton Co. Square, Ste. 188, Noblesville, In 46060

STATE OF INDIANA HAMILTON COUNTY

IN THE HAMILTON CIRCUIT COURT

IN THE MATTER OF THE PETITION

88:

OF OLIVER P. SHORMAKER

No. 24204

FOR Repair of the Oliver P. Shoemaker Drain, or John E Sutton Drain Report of Drainage Commissioners and Engineer.

To the Honorable Judge of the Hamilton Circuit Court.

We the undersigned Commissioners of Drainage and the Engineer, to whom the above entitled petition for Drainage of certain lands in Noblesville, Fall Creek and Deleware Townships, Hamilton County, Indiana, was referred.

We would respectfully report that we met in the Auditors Office, on the <u>25th</u> day of <u>February</u> 1931, qualified and proceeded to View said Drain and lands effected thereby.

After a careful investigation of the condition of said proposed Drain, we are of the opinion that said Drain should be constructed and in the manner set out in this report and that the same when completed will improve the Public health and will reclaim certain lands, and will be a Public utility, and will benefit highways, also that the cost of Constructing, damages and expense of effecting said Drain will be less than the benefits to the lands effected by said Drainage. That we definately determined the best and cheapest method of effecting the drainage of such lands, we have fixed the Route, Location and character of said proposed work and have fixed the same by metes and bounds, courses, descriptions and guides and B noh Marks, for a complete cutlet for the drainage of said lands effected by said proposed work; that we divided the Ditch into sections of not more than 100 feet in length by setting stakes at each 100 feet.

## LOCATION.

Begining at Station 94 plus 50, on Oliver Sheamaker or John H. Sutton Drain at End of tile, Run South 30 degrees and 30 minutes West 650 feet; Thence 23 Degrees West 900 feet; Thence South 425 feet; Thence South 39 degrees West ## ####### 575 feet; Thence South 15 degrees West 400 feet; Thence South 12 Degrees Hast 726 feet, and terminating in Britton Branch, It is our opinion, and report that said repair From Station 94 plus 50, at end or John E Sutton Ditk, of the tile portion, to Station 110 the end of Old Ditch, would best be accompplished by cleaning out to the present grade and width in bottom of 18 inches, and resloping Banks, cleaning and grubbing Right of way, and straightening the channel at station 109 plus 25, to station 109 plus 80, and that from Station 110, to extend and make a part of this Ditch to Station 131 plus 26, and which enters Britton Branch.

Said Ditch to be constructed by excavating all earth, Mud, sluch, boulders, rocks and stone from bed of said Ditch, to insimilate depth and widthas shown on the tabulated statement of cuts and widths. Said tabulated showt is hereby made a part of this report.

All materials excavated shall be equally distributed on ine both banks, by alternating the lifts, and shall be deposited not nearer than four (4) feet from break of banks ( meaning the line as indicated by slope with general elevation of the ground ). Except where the Superintendent of construction might otherwise Order. Said materials not to be left in heaps or piles. Shall not be more than twelve (12) inches deep. Said Ditch shall be Out true to line and grade, and widths given by this report, and shall have side slopes of 1, to 1, or 45 degrees. All trees, stupps, briars, and weeds to be Out, grubbed and removed from banks for a distance of 25 feet on each side from center line of the Ditch. From Station 94 plue 50 to Station 110, shall be 18 inches wide in Bottom, From Station 110, to Station 131 plus 26 or terminus shall be 3 feet wide in bettem.

Oliver	Shomakor	Drain,
--------	----------	--------

Sta	GroundGut,	NudCut,	Width in Bottom,	Gu. Yd s
94-50,	6,88	1,68	1	-
95,	7.51	1.41	錬	10
96,	7,52	1, 33	· 孝单	14
97,	7.58	1, 53	<b>#</b>	16
98,	7,84	0, 89	<b>M</b>	1.3
99,	6,85	1.15	ψ\$	10
100,	6,88	1. 28	<b>#</b>	13
101	6.09	1, 29	<b>A</b>	14
102,	6.45	0, 77	<b>*</b>	12
108,	6	0.89	<b>4</b>	9
104,	6, 38	1.02	<b>#</b>	10
105,	6, 38	0,83	<b>()</b>	10
106,	5, 64	0.69	<b>M</b>	7
107,	5.45	0.80	91	7
1.08,	4,70	0,64	時	7
109,,,,	, 4.55	0 <b>. 64</b>	0	9
110, 111,	3, 61 4, 71	1.01	8 2 AA	35 13
112,	4. 86	1,11 1,31	2,00 # 111	and and
113,	3.96	1.31	釉 黄枝	16 18
114	4.50	1,48		
115	4.28	1.68	積 辨料	19 56
116	3,76	1.68		23
117	3,83	1.43	81 61 <b>28</b>	88
118	3, 43	0.98	财 扶持	18
119	2,88	0.98	11 11 11	14
120	3,65	0,90	11 N H	14
121	3, 65	0.85	辨 理理	13
122	4.25	1.40	神神神	17
123	4,00	1.70	第二件封	22
124	3,60	2,10	性相性	28
125	3.90	1.75	3,00	37
126	4.04	1.69	1997 - 1997 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 - 1997 -	33
1.87	3,99	1.79	胡 韩翔.	94
128	5,14	2.19	利 任務	40
129	4.39	2.34	教教教	45
130	3.54	1.74	80 89 FF	40
131	3, 50	1,19	40 H) (H)	26
131-26	8.44	0.44	\$\$ \$2.98	4

13126

Estimated cost of construction including,
Material, Labor, Hauling, etc.,
Necessary for the completion of the work in
accordance with the Blans & Specifications,
Excavation
Clearing and grubbing,
Tets1, \$ 350.00
Estimate expenses, including,
Atterney Pees
Recording and releating,
Logal Printing,
Superintendent of Construction,
Court expenses sta.,
Contingency fund,
Total, \$ 248.45 Damages Total 273.45 We claim for services, expenses & Mileage, to date for;
Silas DeVaney, Drainage Commissioner, \$ 15.00 Pridary 28- 31
Silas DeVaney, Drainage Commissioner,
R. D. Horney, Engineer & Helpers,
Total, # 94.35

Grand Total,

\$ 718.00

Olivar Shogmacker. Raconstruction John E Sutton.

Å.

= / =

NAMES	DESCRIPTION	OF LANDS	- цо	lownship	- -	Ass	cres sessed	Acres Benefited		Amount of Benefits		Am't of Assessment		t Assessmen	
			Section	Town	Range	A	Hun	A	Hun	\$	Cts.	\$	Cts.	\$	Cts
P. ShogMacker	5,E,	5W.	17	- 18	ۍ م	40	00	40	00	39	00	30	00	30	00
ohn HGwinn.	Pt S.W.	SE.	17	18	5	20	00	20	00	18	20	12	00		
Do.	PHNE	NE	28	18	5	15	00	1.5	00	q	90	9	00	21	00
40°0.	Dt N.E	N	40		5.			-							
<u>)2: J. +</u>	124 - E	Nº=	ريستي	18	 		20	, #	· · · · ·						
1127 Pray Call				* 	د نړ										
obt L. Darrah.	NW 10 a Off			18	<u>٦</u>	40	00	40	00	26	40	24	00		
Do.	oN'	•	1	18	5	10	00	10	00	8	25	7	50	31	50
go Myoung.	5 W	NE	20	18	5	40	00	40	60	26	40	24	00		
Øo.	SE	NW	20	18	J	40	00	40	00	<del>33</del>		30	00		
Do.	SW	NW	20	18	S	40	00	40	00	33	00	30	00		
Do.	NW	NW	20	18	5	40	00	40	00	73	00	30	00		
100. ·	joa off NE	W <del>ost in</del> NW		18	5	30	00	30	00	24	75-	22	57		
000	NW	SW	20	18	5	40	00	40	00	24	40	24	00		·
ão.	W <sup>2</sup> NE	SW	20	18	s	20	00	20	00	13	20	12	00	172	50
lary BCastetter	ENE	- <i>SW</i>	20	18	J <sup>-</sup>	20	00		00	13	20	19	00	12	00
S.Krause	Pt Nr	SW	20	18		18	00	18	<b>40</b>	1(	84	10	90	10	80

Oliver Stroamacker. Reconstruction John E Sutton

ł

														•	
N A 34720	DESCRIPTION O		ų	hip	4		res essed	Acres Benefited		Amount of Benefits			i't of sment		otal ssmen
NAMES		JF LANDS	Section	Township	Range	A	Hun	A	Hun	\$	Cts.	\$	Cts.	\$	Cts
Floyd USutton	NE	N.E.	19	18	5	40	00	40	00	33	00	30	00	30	00
Do.	E'NW.	N.E.	19	18	5	20	00	20	00	[3	20	12	00	42	00
Farn Olson	. <i>S.E</i> .	N.E.	19	18	S	40	00	40	00	33	00	30	00		
Bo.	E <sup>2</sup> SW	N.E.	19	18	-ى	20	00	20	00	16	50	16	00	45	00
Tamily A Sutton	NE	S,E,	19	18	5	40	00	40	00	33	00	30	00		
Do.	EZNW	5.E.	19	18	5	20	<i>ă</i> 0	20	00	<i>!</i> £	50	15	00	45	00
Kittig M Sutto	APt SE,	5, <u>E</u> ,	19	18	5	20	00	20	00	13	20	12	00	,	
Do.	S.W.	SE,	19	18	5	40	00	40	00	16	40	24	00		
Do.	5,E,	5,W.	19	18	Ţ	40	00	<i><b>40</b></i>	00	33	00	30	00		
Do.	N,E,	5.W.	19	18	5	40	00	40	00	33	00	30	00		
Øc.	W2 NN	1. S.E.	19	18	5	20	00	20	00	(6	50	15	00		
Do	Wr S.W.	N,E.	19	18	5	20	00	20	00	(f	40	15	de		
NO.	Wr N.W.	N,E,	19	18	5	20	00	20	00	13	20	12	00	138	00
Elmor O Whit morgtwi	Pt E <sup>2</sup> NA	É, N.W.	19	18	سی	2	00	2	00	1	32	(	20	1	20
<u> </u>	<b></b>			·											
VIII Hatt + Wite				1		1				•	40		00	2#	
the second s	PENE. NU		[	1			00		00	3 - 16	90 50		00' 00'	3	00
<u>Anna C Duncari</u> Do.	SW.	SW.	19	18	5	40	00 00	40	00		40		00	8	00

This copy printed from the Digital Archive of the Hamilton County Surveyor's Office; One Hamilton Co. Square, Ste. 188, Noblesville, In 46060

= 2=

CIIVEr Shoqmaner. Raconstruction John E Sutton.

	·····		•										······	·	
NAMES	DESCRIPTION OF LA	T LANDS		ship			res essed	Acres Benefited		Amount of Benefits					otal ssmeni
	12 15 h		Section	Township	Range	A	Hun	A	Hun	\$	Cts.	\$	Cts.	\$	Cts.
John J Killgy			30	18	5	25	00	25	00	19	37	(	25-		
KOo,	ot SW Oredet f	NW In D	30 au	18 1 aj	J" Jes	.31	43	31	43	15	55-	14	15-	25' Z.5	40
Susie Fisher	Pt NE	NW	30	18	F	15	00	15	00	9	90	9	00	9	00
Harry A Kidwell	PH NW	SW.	30	18	5	/	00		00		<i>ç</i> 0		45-		45-
Len Frazier	A NW	sul.	30	18	5-	3	00	3	00	1	•8	(	35-		34-
Emma Killry	A NW	SU	30	/8	حى		00		00		50		45		45-
Vermont Baptist State Convention	2A, out of N. NE	E.Cor. SE	25	18	4	2	00	2	00	_/	00		90		90
Imer Beaver & wife	IA.out SE. SE	Cor, NE	25	/8	4	_/	00		00		40		45-		45-
Hamilton County	Benefit top I-N&S Be					<u>}</u>				ll	00	10	00		
	1- Et W Three										40		00	15	80
	1-N&S Thro					_)				5	50	_ 5]	00	20	00
Fall Creek Twp	Benchit to Pu 1- Et W Thm	blic Hig Cater	4w 20	a ' 18	5	N i N				4	50		00	ç	00
Delaware Township	Benegitta Pa I-EYW Three	ublic H. Conter	19	78 78	5					. 92	00	20	00	20	00
Viehle Plate R A	NAS Thos	24	19	18	5		· · ·								
Po	NES ·· N	Wiy	<u> 10</u>	18	5-		<u> </u>			22	00	20	00	20	00
· · · · · · · · · · · · · · · · · · ·															
	· · · · ·	•													
<u></u>	     	۰ 													
			   			÷.		·					 		; ,

= 3=


State Of Indiana ) 55 Hamilton County )


> We the undersigned Viewers and Engineer, to whom was referred the above entitled potition for report, after being Duly Sworn upon Oath say that we have personally axamined the whole line af said proposed Ditch, that the assessments herein made and report are correct, just and equitable to all parties herein nemed as interested, that no other lands will be benefitted or injured by said proposed drain, and that the above and foregoing report is true in substance and in fact as we verily believe.


Dilas Peranery


RUHorney Busineer


Clerk of Hamilton Circuit Court.






















March 27, 1998

## **TO: Hamilton County Drainage Board**

RE: Oliver Shoemaker Drain, Arm #3

Attached is a petition for a partial vacation of the Oliver Shoemaker Drain. MSE Corporation on behalf of AMLI filed this request. The request is for Arm #3 of the drain, which a portion is located on the AMLI Property.

Arm #3 begins North of 141st Street on the AMLI Property. Per a report to the Board on April 25, 1983, the total length of Arm #3 was 1000 feet. Per my report of April 21, 1996 the portion of Arm #3 which crosses

the Woods of Britton Apartments was vacated and the This copy printed from the Digital Archive of the Hamilton County Surveyor's Office; One Hamilton Co. Square, Ste. 188, Noblesville, In 46060 Arm was intercepted by the new drainage system for the apartments North of 141st Street.

AMLI will be replacing the existing Arm #3 with a detention facility. Therefore, I recommend to the Board that the remainder of Arm #3, from STATION 0 to STATION 5+00 be vacated.

Kenton C. Ward Hamilton County Surveyor KCW/no

