

Source Document Log
Source Document Discrepancy Log

Drain: CAREY COMMONS DRAIN

Main/Arm Name	Document Name	Document ID	Info From Document	If Applicable	
				Document w/ Discrepancy	Description of Discrepancy
SECTION 1	SURVEYOR'S REPORT	6-25-98			
	SURVEYOR'S REPORT	3-22-99			
	AS BUILTS	28472			
	BAND	6-12-98			
	CERT. OF COMPLIANCE	10-26-98			
SECTION 2	SURVEYOR'S REPORT	7-30-99		SURVEYOR'S REPORT 7-7-03	LENGTH OF SSD IS 1616' ON REPORT
	SURVEYOR'S REPORT	7-7-03		AS BUILTS	SSD SHOWN AS 1757' ON AS-BUILTS
	AS BUILTS	28472			
	BAND	3-16-99			LENGTH OF SPAN FROM STR 822 TO MH IS 121', NOT 120'
	CERT. OF COMPLIANCE	9-23-99			