

Drain: Saddle Creek Drain

Improvement-Arm: Ditch Road Improvements (136th St. to 141st St.)

Date Approved: June 9, 2008


Drain Input Checklist

- Create Regulated Drain Record in Posse _____
 - Drain Type
 - Outlet (Tab)
 - Outlet Attached
 - Location
 - Twp
 - Certification
 - Drain Number

- Enter Improvement Arm in Posse _____
 (Construction Amount = Storm Drains, Erosion Control, Sub-surface drain & Earthwork)

- Scan Documents _____
 - Surveyor's Report
 - Engineer's Estimate
 - Notices
 - Findings and Order
 - Petition

- Create Posse Inspection Job _____
- Enter into Watershed Summary Spreadsheet _____
- Check for Vacation of Drain & Map Changes _____
- Check Drainage Easement Classification _____
- Sum drain length & Validate in GIS _____
- Enter New Watershed Length into Posse _____
- Create Boundary of Improvement in GIS _____



SURVEYOR'S OFFICE
Hamilton County

Kenton C. Ward, CFM
Surveyor of Hamilton County
Phone (317) 776-8495
Fax (317) 776-9628

Suite 188
One Hamilton County Square
Noblesville, Indiana 46060-2230

To: Hamilton County Drainage Board

June 5, 2008

Re: Saddle Creek Drain, Ditch Road Improvements from 136th St. to 141st St.

Attached are petition, plans, and other information for the Ditch Road Improvement from 136th St. to 141st St. This reconstruction was petitioned by the City of Carmel. An inspection of the drainage facilities for this project has been made and the facilities were found to be complete and acceptable.

This report will serve as an initial and final report for this reconstruction. This road project began just north of 136th St. and continued north to 141st St. During this construction the Saddle Creek Drain was affected. Those changes are as follows:

Saddle Creek Drain

Saddle Creek Section 1 Arm: The project removed a portion of the existing drain shown on the plans prepared by Paul I. Cripe, Inc., Job No. 960324-20000, dated August 19, 1996, Sheet C201 between Structures 755-754 and Structures 754-754A. As a result 56' of 12" RCP was removed from this drain. This is shown on sheet 6 of the plans prepared by Beam, Longest and Neff, LLC, Project No. 04-06, dated December 28, 2004.


Saddle Creek Section 4 Arm: The project removed Structure 765 and 74' of 12" RCP as shown on the plans prepared by Paul I. Cripe Inc., Job No. 86032A-20000, dated May 22, 1998 Sheets C201 and C202.. A new structure (Structure 40) was set on this existing run of pipe. Also removed was a riser and 708 feet of 6" SSD that outleted into Structure 765 was removed. Structure 782 was removed and replaced with a new inlet structure. The riser and 395 feet of 6" SSD that outleted into Structure 782 was also removed. Therefore, 1,117 feet of drain was removed from this section as shown on Sheets 7, 8 and 9 of the plans prepared by Beam, Longest and Neff, LLC., Project No. 04-06, dated December 28, 2004.

The road improvements project removed a total of 1,233 feet from the Saddle Creek Drain.

Upon approval of the reconstruction I recommend the Board approve the drain's construction as complete and acceptable.

The work was completed within the right of way owned by the City of Carmel and paid for by the City. Therefore, the project falls under the requirements as set out in IC 36-9-27-52.5. I recommend the Board approve the project at this time.

Sincerely,



Kenton C. Ward, CFM
Hamilton County Surveyor

KCW/pll